

***JAK2 V617F Mutation Detection***  
**#83872**

**EXPLANATION:** #83872, *JAK2 V617F Mutation Detection*, will become obsolete on November 3, 2009. Please order this testing using the new test codes outlined below. See the specific New Test notices for additional information.

**RECOMMENDED ALTERNATIVE TESTS:**

#88715/ *JAK2 V617F Mutation Detection*, Blood

#31155/ *JAK2 V617F Mutation Detection*, Bone Marrow

#31156/ *JAK2 V617F Mutation Detection*, Varies

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or  
Julie Breider, Mayo Medical Laboratories' Technologist Support  
Telephone: 800-533-1710