

MULTIPLE TEST REFERENCE VALUE CHANGES

EXPLANATION: Effective April 6, 2011, Mayo Medical Laboratories will be changing the way reference values are reported and flagged on several tests. Indeterminate and positive results for tests listed below will flag as abnormal and contain an interpretive comment. This will affect test set-up information on all tests and profiles that include any of the unit codes below.

Unit code	Test name	New Reference Value
80179	Jo 1 Ab, IgG, S	<1.0 (Negative)
81358	Sm Ab, IgG, S	<1.0 (Negative)
81357	RNP Ab, IgG, S	<1.0 (Negative)
80178	Scl 70 Ab, IgG, S	<1.0 (Negative)
9278	Centromere Ab, IgG, S	<1.0 (Negative)
87837	Ribosome P Ab, IgG, S	<1.0 (Negative)
81360	SS-A/Ro Ab, IgG, S	<1.0 (Negative)
81359	SS-B/La Ab, IgG, S	<1.0 (Negative)
8178	DNA Double-Stranded Ab, IgG, S	<5 (Negative)

NOTE: One or more of the unit codes above may be components of the profiles listed below.

Unit code	Test name
89035	Antibody to Extractable Nuclear Antigens, S
82403	SSA/SSB

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or
 Brad Bellin, Laboratory Technologist Resource Coordinator
 Telephone: 800-533-1710