

**REPORTING CHANGE**
**NOTIFICATION DATE:** October 26, 2011

**EFFECTIVE DATE:** November 18, 2011

**PI-Linked Antigen, Blood**

Test ID: PANH

Secondary ID: 81156

**Please disregard previous notice sent October 19, 2011- use information below for this reporting change.**

**EXPLANATION:** The unit code for the Flow Cytometry Interpretation, 9-15 Markers will be updated for this assay.

**Current Reflex Tests:**

Unit Code	Reporting Name	Available Separately	Always Performed
31845	Flow Cytometry Interp, 9-15 Markers	No	No

**New Reflex Tests:**

Test ID	Second ID	Reporting Name	Available Separately	Always Performed
FCIMS	88466	Flow Cytometry Interp, 9 to 15 Markers	No	No

**Testing Algorithm:** When flow cytometry results are positive for PI-linked antigens, pathologist review and interpretation will be performed at an additional charge.

**MML List Fee:**

\$361.80

The following test(s) may added per the testing algorithm:

\$111.50 for #88466 Flow Cytometry Interpretation, 9 to 15 Markers

**CPT Code Information:**

PI-Linked Antigen, Blood

88184-Flow cytometry, RBC

88184-Flow cytometry, WBC

88185-Flow cytometry, each additional marker, RBC

88185 x 6-Flow cytometry, each additional marker, WBC

Flow Cytometry Interpretation, 9 to 15 Markers (if appropriate)

88188

**NOTE:** This change may impact test set-up information and could require a change to file definition. Please review the Test Set-Up information for specifics at <http://www.mayomedicallaboratories.com/test-notifications/index.html>.

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or Julie Breider, MML Laboratory Technologist Resource Coordinator  
 Telephone: 800-533-1710