



MAYO CLINIC
Mayo Medical Laboratories

TESTING KIT RECALL

NOTIFICATION DATE: December 6, 2012

EFFECTIVE DATE: Immediately

FERTILITY-TEST YOLK BUFFER (SPERM ANTIBODY) KIT Supply T356

NOTE: Your facility has been identified as one that may have received defective fertility kits used for Antisperm Antibody, Semen testing (SAAS). Please **discard** any unused Fertility-Test Yolk Buffer kits (T356) that you have in stock. Re-order supplies in your normal fashion or ask for over-night delivery. We apologize for any inconvenience.

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or
Marvin H. Anderson, Jr., MML Laboratory Technologist Resource Coordinator
Telephone: 800-533-1710