

REPORTING TITLE CHANGES

NOTIFICATION DATE: July 23, 2009

EFFECTIVE DATE: August 18, 2009

EXPLANATION: To make our test reporting names more logical for clinicians and others who are searching for a test name, these Microbiology tests will undergo a Reporting Title change.

Unit Code	Current Reporting Title	New Reporting Title
50009	Culture, Brucella	Brucella Culture
50011	Culture, Anaerobic Actinomyces	Actinomyces Culture
50001	Culture, Aerobic Bacteria	Bacterial Culture, Aerobic
50003	Culture, Aerobic Bacteria, Sputum	Bacterial Culture, Aerobic, Respiratory
50002	Culture, Aerobic Bacteria, Throat	Bacterial Culture, Throat
50004	Culture, Aerobic Bacteria, Urine	Bacteria Culture, Aerobic, Urine
50010	Culture, Anaerobic Bacteria	Bacterial Culture, Anaerobic
50005	Culture, Enteric Pathogens, Stool	Enteric Pathogens Culture, Stool
50008	Culture, Legionella	Legionella Culture
8135	Culture for Beta Hemolytic Strep	Beta Hemolytic Strep Culture
8116	Culture, Gardnerella vaginalis	Gardnerella vaginalis Culture
8192	Culture, Ureaplasma urealyticum	Ureaplasma urealyticum Culture

NOTE: Specimen requirements will not change for the above unit codes.

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager
Jeremy Caddell, Mayo Medical Laboratories' Technical Support
Telephone: 800-533-1710



MAYO CLINIC
Mayo Medical Laboratories

TEST DEFINITION

7/24/2009

ORDER CODE	EFF DATE	TC	TITLE	CHECKING NORMALS	PRINT NORMALS (# CODED)	PERFORM SITE *
50001	6/30/2008		BACTERIAL CULTURE, AEROBIC			MCR
			TRANSPORT TEMP : AMBIENT\REFRIG (NON-STERILE SOURCE) OK\FROZEN NO			
			50031 SPECIMEN SOURCE			
			50032 RESULT			
			50033 SPECIAL INFORMATION			
			50034 REPORT STATUS			

*PERFORMING SITE LEGEND

```

=====
==
MCR      MAYO CLINIC DPT OF LAB MED & PATHOLOGY      LAB DIRECTOR:  FRANKLIN R. COCKERILL, III, M.D.
          200 FIRST STREET SW
          ROCHESTER, MN 55905
=====
==

```