

**MYOSITIS ANTIBODY PANEL**  
**#91544**

**EXPLANATION OF CHANGE:** The following changes are *effective immediately* for Unit Code 91544, Myositis Antibody Panel, referred to RDL Reference Laboratory, Inc. Upon review of RDL Reference Laboratory, Inc. requirements we have modified the following:

**CURRENT CPT CODE**

86235\MI-2  
86235\PL-7  
86235\PL-12  
86235\EJ  
86235\OJ  
86235\KU  
86235\SRP  
86235\U2 SNRNP

**NEW CPT CODE**

83516\MI-2  
83516\PL-7  
83516\PL-12  
83516\EJ  
83516\OJ  
83516\KU  
83516\SRP  
83516\U2 SNRNP

**REPORTING UPDATE**

This test was developed and its performance characteristics validated by RDL Inc. The FDA has determined that such clearance or approval for these tests is not necessary. This is an analyte specific reagent (ASR) test.

QUESTIONS: Contact Mayo Medical Laboratories  
Telephone: 800-533-1710

To obtain test set-up information contact MML Client Support or log on to:  
[MayoMedicalLaboratories.com/test-notifications](http://MayoMedicalLaboratories.com/test-notifications)