



MAYO
Mayo Medical Laboratories
1-800-533-1710

TESTING RESUMED

NOTIFICATION DATE: July 11, 2013

EFFECTIVE DATE: July 12, 2013

PLATELET ANTIBODY, SERUM

Test ID: PLAB

Secondary ID: 8538

EXPLANATION: The reagent shortage for this test has been resolved. Test code PLAB will be reactivated on July 12, 2013.

NOTE: The temporary referral test, FPLAI, sent to ARUP will be made obsolete on July 12, 2013. Please see a separate announcement for FPLAI for more information.

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or
Richard Einerson, MML Laboratory Technologist Resource Coordinator
Telephone: 800-533-1710