

Laboratory Service Report

1-800-533-1710

Patient Name	Patient ID	Age	Gender	Order #
SAMPLEREPORT,HE42	SA00060813	36	F	SA00060813
Ordering Phys CLIENT,CLIENT		·		DOB 06/05/1977
Client Order # SA00060813	Account Information			Report Notes
Collected 08/15/2013 13:01	C7028846-DLMP Rochester 3050 Superior Drive			
Printed 09/16/2013 13:28	Rochester, MN 55901			

Test Flag Results Unit Reference Value Site*

RECEIVED: 08/16/2013 14:34 REPORTED: 08/16/2013 14:35

FHE4/HE4 results obtained through Mayo Medical Laboratories prior to 09/05/2013 are on average 28% lower than with this assay. Samples assayed with the current method will be available for 6 months for rebaselining if necessary. Contact Mayo Medical Laboratories at 1-800-533-1710 to request this service.

The testing method is an electrochemiluminescence assay manufactured by Roche Diagnostics Inc. and

Values obtained with different assay methods or kits may be different and cannot be used interchangeably.

performed on the Modular or Cobas system.

Test results cannot be interpreted as absolute evidence for the presence or absence of malignant disease.

* Performing Site:

SDL Mayo Clinic Laboratories - Rochester Superior Drive 3050 Superior Dr. NW Rochester, MN 55901 Lab Director: Franklin R. Cockerill, III, M.D.

Patient Name	Collection Date and Time	Report Status
SAMPLEREPORT,HE42	08/15/2013 13:01	Final
Page 1 of 1		** End of Report **