

<b>Patient Name</b> SAMPLEREPORT,HIVE N	<b>Patient ID</b> SA00046008	<b>Age</b> 40	<b>Gender</b> F	<b>Order #</b> SA00046008
<b>Ordering Phys</b>				<b>DOB</b> 09/28/1971
<b>Client Order #</b> SA00046008	<b>Account Information</b>			<b>Report Notes</b>
<b>Collected</b> 06/06/2012 08:59	C7028846-DLMP ROCHESTER 3050 SUPERIOR DRIVE ROCHESTER,MN 55901			
<b>Printed</b> 09/14/2012 08:01				

Test	Flag	Results	Unit	Reference Value	Perform Site*
HIV-1/-2 Ab Evaluation, S		Negative		REPORTED 09/13/2012 09:56 Negative	SDL
If this test is ordered as a follow-up test to a reactive rapid HIV antibody test result, supplemental testing by Western blot is recommended, even when the current test result is negative.					

\* Performing Site:

SDL	Mayo Clinic Laboratories - Rochester Superior Drive 3050 Superior Dr. NW Rochester, MN 55901	Lab Director: Franklin R. Cockerill, III, M.D.
-----	---	--

<b>Patient Name</b> SAMPLEREPORT,HIVE N	<b>Collection Date and Time</b> 06/06/2012 08:59	<b>Report Status</b> Final
Page 1 of 1		** End of Report **

\* Report times for Mayo performed tests are CST/CDT