

LUPUS PANEL
#30537

EXPLANATION: Effective April 6, 2011, Mayo Medical Laboratories will be changing the way reference values are reported and flagged on several tests. Indeterminate and positive results for profile components listed below will flag as abnormal and contain an interpretive comment. This will affect test set-up information for the components listed below in test #30537, Lupus Panel.

Unit code	Test name	New Reference Value
81358	Sm Ab, IgG, S	<1.0 (Negative)
81357	RNP Ab, IgG, S	<1.0 (Negative)
80178	Scl 70 Ab, IgG, S	<1.0 (Negative)
81360	SS-A/Ro Ab, IgG, S	<1.0 (Negative)
81359	SS-B/La Ab, IgG, S	<1.0 (Negative)
8178	DNA Double-Stranded Ab, IgG, S	<5 (Negative)

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager or
Brad Bellin, Laboratory Technologist Resource Coordinator
Telephone: 800-533-1710